
Wire on "top"

Wire Facing "back"


Reference point where wire goes into the sensor
Facing "back"



Wire on "top"

"bump in wire for movement"


Incorrect
Correct


90 degrees, better setup
Too much angle
90 degrees, better setup
Too much angle